



READ AND FOLLOW ALL WARNINGS AND PRECAUTIONS, PROTECT SUPPOUNDING AREA. FROM OVERSPRAY, DO NOT SPRAY ON CLOTHING, FURNITURE OR CAPPET.

DIRECTIONS FOR USE: WAKE NECESSARY WALL REPAIRS BEFORE APPLYING, SPUT PRINE REPAIR APEA BEFORE TEXTURE APPLICATION TO ENSURE BEST RESULTS. Priming after texture application is no longer needed. Always practice spraying on cardioend or scrap drywall to determine

2. REMOVE safety tab from top of trigger. REMOVE radicip from below prezsure triggle. RETAIN radicip and reattach for storage.

POINTING AWAY FROM FACE, TURN YELLOW SPRAY TIP TO DESIRED PATTERN: CLOCK WISE for FINE. COUNTER CLOCKWISE IN HELVY

MOVE VEILOW TO GELE: MONE TELLOW TOBBLE:
"As conducts and pressure in can decrease
adjust pressure and pattern to maintain a
constibut testure appearance.

5. SPRAY at a distance of 18"-24" from wall using S. SPFAY at a destance of 18"-24" from wall using a circular feet sweeping) motion. Notes Depending upon PRESSURE & PAYTERPH settings, distance may vary. Sprays less between 65-80" F. Apply in random partiern, covering only 80% of surface. Stake can occasionally throughout use. CRYYTHE Allow to dry 20 minutes before painting. Herwise teatures may require languer dry time, dependent upon temperature and humbdity.

CLEAN-UP: Warm water

A. AFTER USE/TO STORE clear need to by turning can upside down, more toggle to high pressure and spany until leature is cleared. Reattach rad dip ander pressure toggle for storage. 7. PAINT with 2 coats or more for complete hide and to match gloss [dependent upon color and paint manufacturer's instructions].

DANGERI FLAMMABLE VAPOR, CONTENTS UNDER PRESSURE. CAUSES EYE, SKIN AND RESPIRATORY TRACT IRRITATION. Contains Calcium Carbonato, Viryl Acylic Copolymer, Tale and Dimethyl Ether (propallant). Vapors may calch fire. Keep away from heat, sparks and flame. Exanguish all flames and sources of ignition during use and until all vapors are gone. Prevent build-up of vapors by opening all windows and doors to achieve cross-vanilation. opening all windows and doors to achieve creas-variation. Stere upright in a cool, dry place. Avoid prolonged exposure to surright and other heat sources that may cause bursting. Do not puncture, incinerate, burn or store above 120°F. Use with adequate vantilation. Avoid breathing vapor and spray nist. Avoid contact with eyes and skin. Ware safety glasses or gogdes. Wash hards after using FRRST AID: For eye contact, fush thoroughly with water for 15 minutes and get medical attention. For skin contact, wash thoroughly with seep and water. I inhaled remove person to fresh air. If breathing does not improve, get medical attention. KEEP GUT OF READH OF CHILDREN, WARNING: This product contains a chemical known to the State of California to cause cancer. WARNING: f you scrape, sand or remove old point, you may release lead dust. LEAD IS TOXIC. Contact the National Lead Information Hotling at 1-800-424-LEAD or log on to www.apa.gov/lead.

METRICAL DI SULTIDA PROJECTIONI DELL'ATTRICAL LA SERVICIONI DEL SULTIDA PROSESSI DEL SULTA DEL SULTA PROSESSI DEL SULTA PROSESS

APPLIES OF USE OF USE OF DESCRIPTION OF THE PROPERTY OF THE PR

SOUTH STATE AS ALL INCOMES AND A STATE AS A parting if mality par member assessmentalities includes members. 5. PR B DDCA 1 was 4 stances for 45 s G cm.

I, M M BADAR I was detected as 40 x 10 cm (17 x 27%) to be pared technolous manufacturity to describe the best deposition to the product of the product of the product of the product of the pared to the product of the

del die y el les instructions del faite son de princie.

PRISER les morres puedes provides provides provides de la companyante, financier les sons de la companyante del la companyante del la companyante de la companyante del la companyant

The Paint Product 900 < 90% PRIME < 1.20

rose Point Product POC < 0 Protects Pos direc. Here set A. France Stand of The Sensor Scoop, Inc. Selection NA 00227 we wherespecially over \$25.



MADEIRISA